

! GAS DETECTION SYSTEM !

1. If you see the red signs „NEVSTUPOVAT“ (Do not enter) or „OPUSŤTE PROSTOR“ (Leave the area) light **ON**, do not enter the lab or leave the lab if you are already working in it.



In this case you can quickly finish your work and close the gas cylinders and other gas lines connected to your device before you leave.

2. If you hear the **ALARM** besides the active red signs, leave the lab immediately through **EMERGENCY EXITS!!!**

